



General Guideline for Quality Record Submission Levels

ITEM	QRS LEVEL	CONTENTS
1	LEVEL I	<ul style="list-style-type: none"> • Submission – Level I <ul style="list-style-type: none"> - Certificate of Compliance <p>Note: Suppliers can use their own Certificate of Compliance template and submit to MDA Space</p>
2	LEVEL II	<ul style="list-style-type: none"> • LEVEL I + <ul style="list-style-type: none"> - Quality Record Submission Cover Page - MDA Space Compliance Checklist <p>Note: Suppliers shall only use MDA Space’s provided Cover Page & Compliance Checklist</p>
3	LEVEL III	<ul style="list-style-type: none"> • LEVEL II + <ul style="list-style-type: none"> - Inspection Report - Photograph of Part - CMM Report (when it is applicable and required by MDA Quality Assurance team) <p>Note: No QA review and approval required prior shipping. Only acknowledgment of receipt of the report required prior shipment.</p>
4	LEVEL IV	<ul style="list-style-type: none"> • LEVEL III + <ul style="list-style-type: none"> - Test Data and Pull test when applicable - Submission of test items such as films and coupons when applicable - Approval from MDA Space Quality prior to Shipment
5	LEVEL V	<ul style="list-style-type: none"> • LEVEL IV + <ul style="list-style-type: none"> - Mandatory Inspection Points - Source Inspection - Test procedures - Complete EIDP Package

For more information on the details of the contents, please look at **4046173 REV A MDA SPACE SUPPLIER QUALITY MANUAL**.

Company Confidential

This document in its entirety is MDA Company Confidential and shall not be produced, disclosed or supplied in whole, or in part, outside of MDA without the prior written consent of an MDA Director or above.

Printed copies are uncontrolled.